

9.1 Operations Report- June and July 2024

Author: Arno Benadie, Chief Operating Officer

1. Leaks and Repairs

1.1 There have been several repairs during this period:

- 21-05 Reset Otaire Pump
- 22-05 connect new tank at Markaraka
- 28-05 Leedstown line, water leak, next to SH1 (fish M's old house) locate broken pipe.
- 29-05 till 31-05 try to locate burst pipes off Leedstown line.
- 02-06 fix water leak on bridge at Dave Munns
- 04-06 Found pipe off Dawsons line and dug new line in around swamp.
- 05and 06 June leak on Bernie Hughs property, replace fittings both side of the creek crossing.
- 13-06 Comms issues HRWS pump stations
- 18-06 prep work for creek crossing Ongo Rd
- 19-06 Comms Issues – Pump Stations
- 23-06 comms issues – Pump stations
- 24-06 replace broken air valve at Nick Tipplings
- 01-07 Water leak on bridge, next to Otwhiti School House
- 03-07 Replace valve and fittings at 1808a SH1
- 08-07 Replace bore cock on Tank 1808a SH1
- 09-07 Leak on main line- Ongo Rd
- 10-07 Fix gateway track – Aldworth road
- 11-07 Covered pipe Ongo Rd
- 12-07 Measure pipe work with Speed for Otwhiti pipe bridge
- 15-07 Dig around reservoir tank & measure boxes lids
- 16-07 Comms alarms- reset.
- 17-07 install new pipe work across Otwhiti Bridge with Speed
- 25-07 Water line to Otamarie tank
- 26-07 Otamarie tank – installed boxes over valves and cleaned filters.

2. General

2.1 Lilburn's job has not been completed; work is on-going.

2.2 No further progress with the Makohine Viaduct water line replacement.

[Click or tap here to enter text.](#)

Recommendation

That the 'Huntermville Rural Water Supply – Operations Report June and July 2024' to the Huntermville Rural Water Supply Sub-Committee be received.